



URGENT SAFETY RECALL NOTICE

You are receiving this notice because you have been identified as an owner of equipment incorporating one of the following models of Tulsa Winch:

1241W

1259W

1541W

Tulsa Winch has discovered that some of its Model 1241W, 1259W, and 1541W winches were delivered to customers with an assembly error. The units in question are missing a retaining ring from the brake driver. Without the retaining ring, the input sun gear can become disengaged from the input planetary gear set. When that happens, ***the winch will drop its load.***

This failure will occur unpredictably and CAN CAUSE SERIOUS INJURY OR DEATH. Affected units may operate satisfactorily for many lift cycles before a failure. ***The extreme hazard presented by this condition requires that affected units be withdrawn from service immediately and that they not be used again until they have been inspected.***

Before using your unit again, inspect it in accordance with the attached instructions. If the unit is missing the retaining ring, telephone Tulsa Winch at 1 918 298 8335 to obtain a retaining ring and assistance in installing it. If needed additional information and a service manual can be found at TULSAWINCH.com. To confirm that this inspection has been completed please fax the serial number and date of inspection to Tulsa Winch at 1 918 298 8301.